

# Fotoregistrering af løsøre

---

Dokument navn: 092179\_B02\_C05 Bilag B3 - Fotoregistrering af løsøre

Adresse: [REDACTED] 9440 Aabybro

Matr.nr.: 6f, Gjøl By, Gjøl

CHR nr.: 092179

Dato: 19-02-2025

Rev. nr.: 0

Rev. dato.: -

---

Udarbejdet af: RLSN

Virksomhedsnavn: Rambøll Danmark A/S

Kontrolleret af: LOV

---

## Indholdsfortegnelse

1	Fotoregistrering af løsøre .....	1
---	----------------------------------	---

# 1 Fotoregistrering af løsøre

	<p>Redekasser og hvalpenet.</p>
	<p>Fodermaskine.</p>
	<p>Hyldevogne.</p>



Fedtpumpe.



Flyttekasser.



Drikkedunke mm.



Læsluser.



Drikkeventiller.



Transportbånd - 2 stk.



Kropstromler - 4 stk.



Skindtromler.



Fælder.



Batterier.



Skabemaskine - 2 stk.



Kompressor.



Fældevogn - 2 stk.



Skrabeautomat mm.



Kropstromler mm.



Trillebør.



Aflivningsvogn.



Koldvandsrenser.





Enkeldyrsaflever.



Sorteringsvogn, hedvandsrensner mm.



Fryser - 2 stk.



Tilbehør.



Tanevogn - 16 stk. og tane.




Klimaanlæg.



Tanemaskine - 2 stk.



Diverse.



Gennemløbsvægt.




Talonmaskine.



Skindrener - 3 stk.



Vogne - 17 stk.

 A white refrigerator is positioned in a workshop. To its left is a blue metal frame, and to its right is a wooden workbench with a cardboard box on it. The background shows a light-colored wall and a hanging rack.	<p>Køleskab.</p>
 A workshop interior featuring a wooden workbench cluttered with various tools and equipment. A window in the background shows a view of trees. To the right, there are metal shelves holding more items. A metal grate is visible in the foreground on the right.	<p>Reol med diverse.</p>
 An outdoor suction unit for skidders, consisting of a blue motor and a white drum, mounted on a wooden frame. It is situated against a yellow brick wall with a corrugated metal roof over the unit. The ground is covered with dry leaves and twigs.	<p>Udsugning til skindrenser.</p>